

Heavy Ion Effects of low voltage LVDS line driver/receiver from National Instruments

Sture Larsson
Stanley Mattsson

Saab Ericsson Space AB, Göteborg, Sweden

**Final Presentation of ESTEC Contract 11407/95/NL/CCN-5, COO-8/III.
Report Reference: ESA_QCA0418S_C**



Backgrounds

- ▶ **No export licence on this LVDS from National Semiconductor**
- ▶ **The 5V version was known to be SEL sensitive before it was modified by the manufacturer**
- ▶ **The 3.3V versions become of interest for us to investigate**



Test samples

Part Type:	Driver DS90LV31B	Receiver DS90LV32B
Manufacturer:	National Semiconductor	National Semiconductor
Date Code	0343A	0343A
Quality:	QML 5962-9865101QFA	QML 5962-9865201QFA
Bias Condition	3,3 Volt	3,3 Volt
Package	FP-16	FP-16
Serialization	S/N 1, S/N 2	S/N 3, S/N 4





Heavy ions used in the present investigation at CYClotrone at Louvain la Neuve

Element	Energy MeV	Range μm	LET value $\text{MeV}\cdot\text{cm}^2/\text{mg}$
84Kr17+	316	43	34.0
84Kr25+	756	92	32.4
132Xe26+	459	43	55.9




Test Techniques



SET measured with a feeding-and-counting technique developed by M.Wiktorson et al.

Partial SEL



Current as a function of test time.

First LU leave the device at about 350 mA, second LU initially at 700 mA.

The LU-protection unit was set to shut down the DUT at 800mA.


For each SEL, the current increase was about 350mA

After the current was shut down by LU-protection unit, the component operated as normal

Both the Driver and the Receiver showed the same behavior and sensitivity for SEL



SEL Cross Section vs LET



No clear threshold value was recorded

Fluence of 1E6 → Few SEL's



Conclusions

- Both the LVDS Driver & Receiver are Single Event Latch-up (SEL) sensitive. This has been known before on the 5V supply versions. After the 5V versions was modified it is no longer LU sensitive. Now the 5V versions “only” show indications of SET’s.
- During the LU mode both the Driver and the Receiver does NOT operate, the data transferring is out of order.
- With a LU-protection the 3.3V versions are useable, since after a shut down a 100% functionality was found.

