

# **Heavy Ion Effects in PWM's of the type UCC1806 and UC1825**

Sture Larsson  
Stanley Mattsson

Saab Ericsson Space AB, Göteborg, Sweden

**Final Presentation of ESTEC Contract 11407/95/NL/CCN-5, COO-8/I.  
Report Reference: ESA\_QCA0417S\_C**



**Saab Ericsson Space**

## Heavy ion tests of 2 types Pulse Width Modulators (PWM),

1/ UCC1806 DC: 0146

2/ UC1825. DC: 0313

Both are from Texas Instrument. The dices come from stock and are manufactured by Unitrode at Merrimac.


### *Heavy ions used in the present investigation at CYClotrone at Louvain la Neuve*

Element	Energy MeV	Range μm	LET value MeV·cm <sup>2</sup> /mg
22 Ne7+	235	199	3.3
40 Ar12+	372	119	10.1
78 Kr25+	756	92	32.4



**Saab Ericsson Space**

## Test Setup for UCC1806



Measured signals and trigger conditions

Signal

Aout

Bout

EA

CL

Vref-out

Rsense

Trig condition

Pulse width < 1μs

no trig

neg. slope at 1.36V

neg. slope at 2.80V


neg. slope at 0.59V

no trig



**Saab Ericsson Space**

## Results from UCC1806



Comparative tests at a LET=32.4MeV/mg/cm<sup>2</sup> for different  
Vref in and different capacitances on Vref out at

C	Vref=1.25V	Vref=2.50V	Vref=5.00V
10nF	4.20E-04	4.10E-04	4.30E-04
150nF	3.80E-04	3.55E-04	4.10E-04

The Cross Section values given in cm<sup>2</sup>




No significant differences




**Saab Ericsson Space**


*Oscilloscope picture indicating that one of the latches in the UVLO is hit by an ion. The CL signal show a short response time.*




*Typical picture of an error generated in some of the OP-amplifiers controlling the UVLO where almost all signals are affected.*



*Oscilloscope picture of measured parameters when negative slope on the CL signal was triggering the oscilloscopes. The Vref starts to decrease at about 10μs before the CL close down the PWM and at the same time the Aout pulse period is shifted.*




## Cross Section vs LET



The above diagram indicate that an ion hit somewhere will influence all signals

## Test setup for UC1825




Measured signals and trigger conditions


Signal	Trig condition
Aout	Pulse width < 3μs
Bout	no trig
SS	neg. slope at 2.60V
EA	neg. slope at 2.00V
Vref-out	neg. slope at 2.80V
5V out	no trig




**Saab Ericsson Space**


## Results from UC1825







## Cross Section vs. LET for UC1825



Trigg on Aout<3μs and EA negative slope show identical cross sections  
A slightly lower cross section was measured when trigger was set on the SS

## Conclusions


- No Single Event Latch-up (SEL) or hard errors were observed for UCC1806 or UC1825
- The cross section for UCC1806 has here been shown to be about 10 times higher than what has been reported earlier. Here a LET threshold value of about  $20\text{MeV/mg/cm}^2$
- The LET threshold value for UC1825 is about  $10\text{Mev/mg/cm}^2$
- The differences in results from earlier tests with UCC1806, can certainly depend on the test setup used




# FINISH



**Saab Ericsson Space**




**Current Limit latch**




**Saab Ericsson Space**

**assumed to be only in the "out-latch"**



**Saab Ericsson Space**

### 311-1-43 (Aout<1μs)



Assumed to be an error in the Error Amplifier



**Saab Ericsson Space**