

Total Dose and Single Event Effects in Commercial PWM's and Gate Drivers

Contract 11407/95/NL COO10 RUAG Report No: D-P-RAD-01218-SE ESA Report No: ESA_QCA0822S_C

Sture Larsson, Stanley Mattsson

RUAG Aerospace Sweden

stanley.mattsson@ruag.com

ESA Technical Officer: Reno Harboe Sorensen



- TID & SEE Tests of 3 PWM's and 3 Gate Drivers
 - TID; 5 biased & 2 unbiased samples tested
 - SEE; 2 samples tested

- One device removed from original list
 - LTC3418 /Linear Technology
 - Monolithic synchronous step-down DC/DC converter
 - 38-lead plastic QFN
 - Difficult to maintain proper function after removing plastic
 - TID failure after ~20 krad

• 2 Pulse Width Modulators

16-lead thermally enhanced TSSOP

- LTC3703, Linear Technology, BiCMOS
 - switching regulator capable of driving multiple MOSFETS for high current application, soft-start function controlled with 100pF

16-lead thermally enhanced TSSOP

- LT3800, Linear Technology, Bipolar
 - fixed frequency high-voltage synchronous current mode stepdown switching regulator, soft-start disabled during irradiation





RUAG

Test Samples Gate Drivers

3 Gate Drivers

- TPS2834 Texas Instruments, BiCMOS synchronous buck driver

UCC27223, Texas Instrument, Bipolar high-speed synchronous buck driver with enable function, - difficult to prepare for SEE

UCC27423, Texas Instrument, Bipolar dual highspeed synchronous buck driver with enable function. - difficult to prepare for SEE

HTSSOP-14







RUAG

14-lead SOIC (D-package)

TID Test Results PWMs



> LTC3707 BiCMOS

Biased; failed ~ 40-60 krad(Si), no recovery during high temperature anneal

Unbiased: no degradation to 80 krad(Si)



•LT3800 Bipolar

Biased; worked up to 80 krad(Si), fail to start after power-off at end of irradiation

Unbiased; fail to function ~ 25 krad(Si)

Biased & Unbiased samples recovered during high temperature annealing.





UCC27223 BiCMOS

Biased; functioning up to 55 krad, after planned power break, 4 of the 5 samples failed to work.

Unbiased; failed before 40 krad

No samples recovered in high temperature anneal



•UCC27423 BiCMOS

(same functions as UCC27223, fewer control possibilities)

Biased; current increase, no failure up to 80 krad

Unbiased; current increase, failure ~75 krad

All samples functioned after anneal





• TPS2834 BiCMOS

Biased; current increase, functioning up to 80 krad

Unbiased; current increase, functioning up to 80 krad

Current recover after high temp anneal





> **TPS2834**

No LU (LET=80 MeV/mg/cm2)

Only very short glitches observed up to LET=80 MeV/mg/cm2

Two outputs; A_out and B_out Trigger requirements on both

- Too-long ON time
- -Too-long OFF time
- Period 6,5µs



Only narrow glitches were detected for TPS2834

8

SEE Test Results – Gate Driver

RUAG

> UCC27223

LU observed at LET=32 MeV/mg/cm2

SEFI first detected at LET=3,6 MeV/mg/cm2

Very SET sensitive with long periods of lost pulses

No "too-long" pulses detected



Current jumps caused by irradiation. The arrow indicates where a reset has been performed by switching off - on the pulse generator to the input





Oscilloscope picture of output A and B showing worse case errors observed during irradiation with Kr-ions tilted at 45° (Let=45.4 MeV/mg/cm2).



> UCC27423

No LU observed at LET=80 MeV/mg/cm2

No SET observed at LET=80 MeV/mg/cm2

?

(The devices were really Working)

SEE Test Results - PWM

RUAG

> LTC3707

No LU (LET=80 MeV/mg/cm2)

Very SET sensitive with long periods of lost pulses

No "too-long" pulses detected



Typical oscilloscope picture, data at 82Kr tilted at 45°, similar behaviour observed for 40 Ar (LET=10 MeV/mg/cm2).

The period time for the PWM was 4.6 $\mu s.$ oscilloscope triggered on A Out OFF-time criteria too long



SEE Test Results - PWM



> LT3800

No LU (LET=80 MeV/mg/cm2)

Very SET sensitive with long periods of lost pulses

No "too-long" pulses detected





Typical oscilloscope picture for OFF time too long on output A and B at the same time. Oscilloscope triggered on A Out

The period time for the PWM was 4.8 μ s.



- PWM's
 - TID Acceptable for short missions/ low irradiation requirements,
 - SEE Not Acceptable
- Gate Drivers
 - TID reasonable results
 - SEE 2 types showed no/small glitches,
 - 2 "similar" Gate Drivers indicated remarkably different results



Thank You