



DOCUMENT CHANGE REQUEST

DCR number 395 Changes required for: General

Date: 2008/02/28

Date sent: 2008/02/28

Originator: Samuel SAVIN

Organisation: CNES

Status: IMPLEMENTED

Title: Diodes, Silicon, Power Rectifier , High Efficiency, Fast Recovery, based on type BYW81-200

Number: 5103/029

Issue: 3

Other documents affected:

Page:

Paragraph 1.8, page 9

Paragraph:

Paragraph 1.8, page 9

Original wording:

Proposed wording:

See attached document

Justification:

Error during implementation of DCR 272:

Functional diagram has not been updated for variant 05, when new drawing added to harmonize this SMD.5 package outline with all other ESCC specification with this STM package

Attachments:

Document_BYW81-200.pdf, null

Modifications:

N/A

Approval signature:

Date signed:


2008-02-28

1.8 FUNCTION DIAGRAM

Variant 05

Terminal 1 and 2: Anode

Terminal 3: Cathode



JUSTIFICATION

Error during implementation of DCR 272:

Functional diagram has not been updated for variant 05, when new drawing added to harmonize this SMD.5 package outline with all other ESCC specification with this STM package.