DOCUMENT CHANGE REQUEST

DCR number 395	Changes required for: General	Originator: Samuel SAVIN
Date: 2008/02/28	Date sent: 2008/02/28	Organisation: CNES
Status: IMPLEMENTED		

Title:	Diodes, Silicon, Power Recitifier , High Efficiency, Fast Recovery, based on type BYW81-200		
Number:	5103/029	Issue:	3

Other documents affected:

Page:

Paragraph 1.8, page 9

Paragraph:

Paragraph 1.8, page 9

Original wording:

Proposed wording:

See attached document

Justification:

Error during implementation of DCR 272:
Functional diagram has not been updated for variant 05, when new drawing added to harmonize this SMD.5 package outline with all other ESCC specification with this STM package


Attachments:

Document_BYW81-200.pdf, null

Modifications:

N/A

Approval signature:




Date signed:

2008-02-28

1.8 FUNCTION DIAGRAM

Variant 05
Terminal 1 and 2: Anode
Terminal 3: Cathode



JUSTIFICATION

Error during implementation of DCR 272:
Functional diagram has not been updated for variant 05, when new drawing added to harmonize this SMD.5 package outline with all other ESCC specification with this STM package.