Typographic error for ESSC 9207/006 issue 5:

Original text (*):

Modified text: The correct pin assignment