

## DOCUMENT CHANGE REQUEST

DCR number 1088 Changes required for: Qualification Originator: Philippe Gerard

Date: 2017/11/13 Date sent: 2017/05/30 Organisation: SOURIAU

Status: IMPLEMENTED

Title:	Accessories for Rectangular Connectors 3401/001 and 3401/002 and Connector Savers 3401/020					
Number:	3401/022	Issue:	11			
Other documents affected:						
Page:						

12
Paragraph:

Dimension table for male screw locks

Original wording:

See current ESCC 340/022 Specification Page 12

Proposed wording:

Correction of the wrong values of dimension Q introduced by the DCR 221511

Dimension Q = 3.22/3.98 for variants 04,05,51,52,67,68,75 and 76(shell size D without back-shell).

See attached draft of modified ESCC 3401022 Specification.

Justification:

Wrong values Q for variants 04,05,51,52,67,68,75 and 76(shell size D without back-shell).

The use of the dimensions of specification 3401022 does not allow locking of the male screw-lock devices in the female screw-locks.

The dimension Q must be identical to the other shell sizes (E, A, B, C)

The dimension Q must be identical for all shell sizes as is the case for versions used with back-shells (see configuration 1) and the models described in configuration 2 used with or without back-shells.

Attachments:
3401022_issue_11_page12.pdf
Modifications:
N/A
Approval signature:
12. Cari-t
Date signed:
2017-11-13