



DOCUMENT CHANGE REQUEST

DCR number 1619 Changes required for: General		Originator: Steve Thacker	
Date: 2024/09/10 Date sent: 2023/12/11		Organisation: ESCC Executive Secretariat	
Status: IMPLEMENTED			

Title:	Relays Electromagnetic Latching 28Vdc 10A 2PDT		
Number:	3602/001	Issue:	5

Other documents affected:

3602/009-8

Page:

See below & attached spec mark-ups

Paragraph:

See below & attached spec mark-ups

Original wording:

as per current issue (3602/001 issue 5 & 3602/009 issue 7)

Proposed wording:

Correct the various figures in regard of the terminal Y1 & Y2 lengths (i.e delete dimension E1) and, where applicable, add the missing header terminal spacing details (dimensions D & D1) as follows.
See attached spec mark-ups for details:

1) 3602/001 Page 10, Variant 05

2) 3602/009 Pages 8 to 13, all Variants
Variants 03/13 & 05/15: correct Y1, Y2 lengths.
All Variants: add missing dimensions D & D1 (by change to figure 1.6.3 & addition of note 2 to all other figures)

Justification:

Correction of errors introduced by earlier DCRs (709 & 1139)

Attachments:
escc3602001iss_draft_6a_in_review.docx, escc3602009iss_draft_8a_in_review.docx
Modifications:
N/A
Approval signature:

Date signed:
2024-09-10