



DOCUMENT CHANGE REQUEST

| | | | | | | | | | | | | | | | |
|---|-----------------------------------|--|--|-----------------------------|--|---------------------------------|----------|--|-----------------------------------|--|-----------------------------------|--|-----------------------------------|--|-----------------------------------|
| DCR number 1763 | | Changes required for: General | | Originator: Philippe Gerard | | | | | | | | | | | |
| Date: 2025/09/30 | | Date sent: 2025/07/24 | | Organisation: SOURIAU | | | | | | | | | | | |
| Status: IMPLEMENTED | | | | | | | | | | | | | | | |
| Title: | | Connectors Electrical Rectangular Removable Crimp Contacts, based on type D*MA | | | | | | | | | | | | | |
| Number: | | 3401/002 | | Issue: 15 | | | | | | | | | | | |
| Other documents affected: | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | |
| Page: | | | | | | | | | | | | | | | |
| 28 | | | | | | | | | | | | | | | |
| Paragraph: | | | | | | | | | | | | | | | |
| APPENDIX B | | | | | | | | | | | | | | | |
| Original wording: | | | | | | | | | | | | | | | |
| <p>Connectors may be ordered without the contact information characteristic code (i.e. -FO) being included in the ESCC Component Number. In which case, unless otherwise advised by SOURIAU during the Ordering process, the contacts, of the appropriate quantity, to be supplied with the connectors shall be as follows:</p> <table><tr><td>Ordered Connector (without -FO)</td><td>Contacts</td></tr><tr><td>340100201BD*MA*P* (with Male Contacts)</td><td>340100501B</td></tr><tr><td>340100201BD*MA*S* (with Female Contacts)</td><td>340100502B</td></tr><tr><td>340100202BD*MA*P* (with Male Contacts)</td><td>340100507B</td></tr><tr><td>340100202BD*MA*S* (with Female Contacts)</td><td>340100508B</td></tr></table> | | | | | | Ordered Connector (without -FO) | Contacts | 340100201BD*MA*P* (with Male Contacts) | 340100501B | 340100201BD*MA*S* (with Female Contacts) | 340100502B | 340100202BD*MA*P* (with Male Contacts) | 340100507B | 340100202BD*MA*S* (with Female Contacts) | 340100508B |
| Ordered Connector (without -FO) | Contacts | | | | | | | | | | | | | | |
| 340100201BD*MA*P* (with Male Contacts) | 340100501B | | | | | | | | | | | | | | |
| 340100201BD*MA*S* (with Female Contacts) | 340100502B | | | | | | | | | | | | | | |
| 340100202BD*MA*P* (with Male Contacts) | 340100507B | | | | | | | | | | | | | | |
| 340100202BD*MA*S* (with Female Contacts) | 340100508B | | | | | | | | | | | | | | |
| Proposed wording: | | | | | | | | | | | | | | | |
| <p>Connectors may be ordered without the contact information characteristic code (i.e. -FO) being included in the ESCC Component Number. In which case, unless otherwise advised by SOURIAU during the Ordering process, the contacts, of the appropriate quantity, to be supplied with the connectors shall be as follows:</p> <table><tr><td>Ordered Connector (without -FO)</td><td>Contacts</td></tr><tr><td>340100201BD*MA*P* (with Male Contacts)</td><td>340100501B replaced by 340100511B</td></tr><tr><td>340100201BD*MA*S* (with Female Contacts)</td><td>340100502B replaced by 340100512B</td></tr><tr><td>340100202BD*MA*P* (with Male Contacts)</td><td>340100507B replaced by 340100517B</td></tr><tr><td>340100202BD*MA*S* (with Female Contacts)</td><td>340100508B replaced by 340100518B</td></tr></table> | | | | | | Ordered Connector (without -FO) | Contacts | 340100201BD*MA*P* (with Male Contacts) | 340100501B replaced by 340100511B | 340100201BD*MA*S* (with Female Contacts) | 340100502B replaced by 340100512B | 340100202BD*MA*P* (with Male Contacts) | 340100507B replaced by 340100517B | 340100202BD*MA*S* (with Female Contacts) | 340100508B replaced by 340100518B |
| Ordered Connector (without -FO) | Contacts | | | | | | | | | | | | | | |
| 340100201BD*MA*P* (with Male Contacts) | 340100501B replaced by 340100511B | | | | | | | | | | | | | | |
| 340100201BD*MA*S* (with Female Contacts) | 340100502B replaced by 340100512B | | | | | | | | | | | | | | |
| 340100202BD*MA*P* (with Male Contacts) | 340100507B replaced by 340100517B | | | | | | | | | | | | | | |
| 340100202BD*MA*S* (with Female Contacts) | 340100508B replaced by 340100518B | | | | | | | | | | | | | | |
| Justification: | | | | | | | | | | | | | | | |
| This DCR is raised on behalf of Manufacturer Souriau and will have no impact other ESCC Manufacturers using this specification | | | | | | | | | | | | | | | |

Attachments:

escc3401002iss16_draft_a_in_review.docx

Modifications:

N/A

Approval signature:



Date signed:

2025-09-30