



DOCUMENT CHANGE REQUEST

| | | | | | |
|------------|-------------|-----------------------|------------|---------------|----------------------------|
| DCR number | 1512 | Changes required for: | General | Originator: | Steve Thacker |
| Date: | 2022/11/14 | Date sent: | 2022/06/09 | Organisation: | ESCC Executive Secretariat |
| Status: | IMPLEMENTED | | | | |

| | | | |
|--------|--|--|--|
| Title: | Fast-Locking Screw Lock Assemblies For Rectangular Connectors 3401/001, 3401/002 and | | |
|--------|--|--|--|

| | | | |
|---------|----------|--------|---|
| Number: | 3401/085 | Issue: | 4 |
|---------|----------|--------|---|

Other documents affected:

3403/004-6

Page:

Paragraph:

Original wording:


Proposed wording:

Justification:

Both specifications have been notified to be discontinued in 2020 by the Manufacturer in the ESCCQPL, i.e,

.....
3401/085; C&K Components; Ref. ESCCQPL Certificate 185K:
"Due to low sales, the product will be discontinued. The possibility of Last Time Buy is the 30/04/2020. Additional details can be found in the Product Discontinuation Notice PDN 19-30."

.....
3403/004; Radiall; Ref. ESCCQPL Certificate 337F:
"Qualified variants from ESCC 3403/004 have been replaced with variants from ESCC 3403/006. ESCC 3403/004 Variants 04 and 05 will be discontinued with a Last Time Buy order possibility up to October 2020."

| |
|--|
| Attachments: |
| N/A |
| Modifications: |
| N/A |
| Approval signature: |
|  |
| Date signed: |
| 2022-11-14 |