



## DOCUMENT CHANGE REQUEST

DCR number 306 Changes required for: General

Date: 2006/12/04

Date sent: 2006/12/04

Originator: S Thacker ESCC

Organisation: ESA/ESTEC

Status: IMPLEMENTED

Title: HCMOS 8 Channel Multiplexer Register with 3-State Latches, based on type 54HC356

Number: 9306/055 Issue: 2

Other documents affected:

9405/016-2

Page:

Page 21 - Para. 2.3.3 Note 5

Paragraph:

Page 21 - Para. 2.3.3 Note 5

Original wording:

Proposed wording:

Amend in Para 2.3.3 Note 5 propagation delay and transition times table as follows:

For "tPZH", "tPZL"; "tPHZ"; "tPLZ" & "tPHL, tPLH, tTHL, tTLH": add CL=50pF


For "tPZL"; "tPHZ"; "tPLZ": RL = 1kohm ( was blank)

For "tPHL, tPLH, tTHL, tTLH": RL = "-" (was "200kohm")

For "tPHL, tPLH, tTHL, tTLH": S2 = "Open" (was "Closed")

Justification:

Typographic errors introduced during previous up-issue (& to be consistent with other ESCC specs in the 54HC series)

Attachments:
N/A
Modifications:
N/A
Approval signature:

Date signed:
2006-12-04