



## DOCUMENT CHANGE REQUEST

DCR number 1187 Changes required for: General

Date: 2019/01/21

Date sent: 2018/11/07

Originator: Steve Jeffery

Organisation: ESCC Executive

Status: IMPLEMENTED

Title: Connector Savers Electrical Rectangular Microminiature, based on type MDM

Number: 3401/041 Issue: 6

Other documents affected:

3401/077-7

Page:

7, 9, 13 & 17 of ESCC 3401/041; 7, 9, 10 & 12 of ESCC 3401/077.

Paragraph:

Table 1(a), Figure 2, Para. 4.3.9 & Figure 4 of ESCC 3401/041;

Table 1(a), Figure 2 of ESCC 3401/077.

Original wording:

See Table 1(a), Figure 2, Para. 4.3.9 & Figure 4 of ESCC 3401/041 Issue 5;

See Table 1(a) and Figure 2 of ESCC 3401/077 Issue 7.

Proposed wording:

See the changes highlighted in yellow in the attached MSWord files.


Justification:

This DCR is raised to incorporate various changes to the specifications (e.g. harmonisation of dimensions, mating forces and unmating forces) as a result of the recently-updated ESCC 3401/029 Issue 16. DCRs 1150 & 1180 refer. Note - an update of these detail specifications was originally requested by O. Masson of C&K Components in June 2018.

It is also raised to correct the following editorial errors in ESCC 3401/077 Issue 7:

In Note 2 to Table 1(a), was "3901/003", corrected to "3901/013".

In the title of Figure 2.4, "SOLID" is deleted (added by mistake during DCR 758 implementation).

Attachments:
escc3401077_draft_8a_for_dcr_review.docx, escc3401041_draft_6a_for_dcr_review.docx
Modifications:
N/A
Approval signature:

Date signed:
2019-01-21