



DOCUMENT CHANGE REQUEST

DCR number		1246		Changes required for: General		Originator: Lindsay Turot	
Date: 2019/05/23				Date sent: 2019/03/06		Organisation: Axon Cable	
Status: IMPLEMENTED							
Title:	High Data Rate Cable Assembly with Microminiature, Rectangular, Coaxial Connectors, based on						
Number:	3409/001		Issue:	2			
Other documents affected:							
Page:							
-							
Paragraph:							
-							
Original wording:							
-							
Proposed wording:							
-							
Justification:							
-							



DOCUMENT CHANGE REQUEST

DCR number 1246 Changes required for: General

Date: 2019/05/23

Date sent: 2019/03/06

Originator: Lindsay Turot

Organisation: Axon Cable

Status: IMPLEMENTED

Title: High Data Rate Cable Assembly with Microminiature, Rectangular, Coaxial Connectors, based on

Number: 3409/001

Issue: 2

Other documents affected:

Page:

7, 8, 9, 23, 24, 25, 26, 28, 30

Paragraph:

See list of changes in the enclosed word & pdf files

Original wording:

See list of changes in the enclosed word & pdf files

Proposed wording:

See list of changes in the enclosed word & pdf files

Justification:

Addition of a new connector variant



DOCUMENT CHANGE REQUEST

DCR number 1246 Changes required for: General

Date: 2019/05/23

Date sent: 2019/03/06

Originator: Lindsay Turot

Organisation: Axon Cable

Status: IMPLEMENTED

Title: High Data Rate Cable Assembly with Microminiature, Rectangular, Coaxial Connectors, based on

Number: 3409/001

Issue: 2

Other documents affected:

Page:

7, 25, 26

Paragraph:

See list of changes in the enclosed word & pdf files

Original wording:

See list of changes in the enclosed word & pdf files

Proposed wording:

See list of changes in the enclosed word & pdf files

Justification:

Update of cable information

Attachments:

esc3409001iss2_(draft2a)___dcr_new_variant+_cable.pdf, dcr_3409001_new_variant+_cable.docx

Modifications:

All changes in the original DCR are acceptable. The following additional changes are required for consistency and clarification purposes (as agreed with manufacturer Axon)

(a) Throughout (editorial errors):

- change references to "Para. 1.4.2.2" to be "Para. 1.4.2.1"
- change references to "Para. 1.6.2.15" to be "Para 1.6.3"


(a) Para. 1.4.2.1, Note 1: add combination: 18 + 00

(b) Para. 1.6.2.14 Note: 3: Amend cable diameter to be 2.5(was 2.4)

(c) Para. 1.7.2: Amend cable type to be AXOWAVE SC25SP (not S25SP)

(d) Para. 2.4 Note: 7: Add code 18 to the list (not 12)

(e) Para. 2.4 Mask Test add code 18 (i.e. ... with codes 10, 11, 18

Approval signature:

Date signed:
2019-05-23