



## DOCUMENT CHANGE REQUEST

DCR number 883 Changes required for: General

Date: 2014/11/17

Date sent: 2014/10/13

Status: IMPLEMENTED

Originator: Steve Thacker

Organisation: ESCC Executive  
Secretariat

Title: Accessories for Rectangular Connectors 3401/001 and 3401/002 and Connector Savers 3401/020

Number: 3401/022 Issue: 8

Other documents affected:

Page:

9 & 10

Paragraph:

Figure 2(a):  
Screw Lock Assembly (Female) (4-40)  
Screw Lock Assembly (Female) (Hybrid 4-40/M3)

Original wording:

see original spec.

Proposed wording:

Amend the 2 figures for Screw Lock Assembly (Female) in Figure 2(a) as follows:


For: Screw Lock Assembly (Female) (4-40):  
Amend the thread definition of the head hole to be: 4.40 UNC-2B  
Add thread definition of the shaft: 4.40 UNC-2A

for: Screw Lock Assembly (Female) (Hybrid 4-40/M3):  
Amend the thread definition of the head hole to be: 4.40 UNC-2B

See attached amended draft spec ("3401/022 issue 9 in progress") for details.

Justification:

Typographical errors introduced during a previous specification revision.

Attachments:
3401022_issue_9_in_progress.docx
Modifications:
N/A
Approval signature:

Date signed:
2014-11-17